Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

U138 2701 W. SIXTH ST NY Spills S103560569
ESE 2701 W. SIXTH ST N/A

1/8-1/4 BROOKLYN, NY 0.243 mi.

1283 ft. Site 4 of 4 in cluster U

 Relative:
 SPILLS:

 Higher
 Name:
 2701 W. SIXTH ST

 Actual:
 Address:
 2701 W. SIXTH ST

 3 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 9405725 / 2003-11-04

Facility ID: 9405725 Facility Type: ER DER Facility ID: 149944 Site ID: 178548 DEC Region: 2 Spill Cause: Other Spill Class: C4 2401 SWIS: Spill Date: 1994-07-27 Investigator: **CESAWYER** Referred To: Not reported Reported to Dept: 1994-07-27 CID: Not reported Water Affected: Not reported Spill Source: Commercial/Industrial

Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Pote False Computer: 1004 10 48

Date Entered In Computer: 1994-10-18
Spill Record Last Update: 2003-11-04
Spiller Name: Not reported
Spiller Company: YORK RESEARCH
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was SAWYER 10/10/95: This Is Additional Information About Material

SAWYER 10/10/95: This Is Additional Information About Material Spilled From The Translation Of The Old Spill File: Comb Liquid Min.

Oil.2-10-03: Closed Due To The Nature / Extent Of The Spill Report.10/27/03 1010 Hrs - Sawyer - Re-Opened Because Of Request For No Further Action Letter.11/4/03 1600 Hrs - Sawyer - The Full File

Including Nfa Letter Was Sent Over By Andrew Desiderio, Who Received The Information From The Jasper Energy Company, The Successor To York

Research Group. Closed."

Remarks: "TRANSFORMER IN STORAGE STRUCK IT W/ BACK HOSE & BROKE A BUSHING.

WILL CLEAN WITH ABSORP. MATERIAL- ITS ON A PAVED AREA."

All Materials:

 Site ID:
 178548

 Operable Unit ID:
 1000037

 Operable Unit:
 01

 Material ID:
 382310

 Material Code:
 0016A

 Material Name:
 non PCB oil

 Case No.:
 Not reported

Map ID
Direction
Distance

Site

Elevation

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

Material FA: Petroleum Quantity: -1.00 Units: L Recovered: .00

Oxygenate: Not reported